B) Wheel hub has to be replaced by a new one

Retrofit kit to upgrade Mosquito and Glasflügel 304 to disk brake

	Description	Drawing	p/n
1.	5" disk brake wheel 122-20	T9365-0	055152
2.	Wheel axle		048563
3.	Brake assembly 30-9 for brake fluid DOT 4	TN0505	075820
4.	Hydraulic fitting, straight		075830
5.	Torque plate assembly with anchor bolt	T9365-2	055751
6.	Master cylinder type 7	T9114-03	058270
7.	Support for master cylinder		
8.	Hydraulic hose type 3a, 900 mm length		058390
9.	Hollow screw with copper gaskets		058550
10.	General arrangement drawing, installation instructions	T9402-0	
11.	Licence charge for certification in Germany (paid to Messrs. Streifeneder)		
	Retrofit kit complete		**051564**

Required work:
Installation of the wheel unit, brake assembly and master cylinder with reservoir, laying of hydraulic hoses, filling and bleeding of the system.

If you have only little experience with hydraulic systems, we would recommend to contact an appropriate work shop to have done that modification.



TOST
Flugzeuggerätebau
Tost GmbH Flugzeuggerätebau München
Thalkirchner Straße 62 ◆ 80337 München ◆ ☎ 089–544 599–0
Fax 089–544 599–70◆e-mail: info@tost.de◆ EASA DE.21G.0065