Retrofit kit to upgrade PW 6 to disk brake

	Description	Drawing	p/n
1	5" disk brake wheel 122-20		055152
5	Brake assembly 30-9 for brake fluid DOT 4		075820
6	Tube fitting straight		075830
7	Torque anchor plate assy		055752
8	Master cylinder type 7	T9114-03	058270
9	Hydraulic hose type 2a, 900 mm length		058490
10	Male stud coupling C3		058670
11	Support for master cylinder from GfK		059514
13	General arrangement drawing and instructions		

Retrofit kit complete

Required work:
Installation of the wheel unit, brake assembly and master cylinder with reservoir, laying of hydraulic hoses, filling and bleeding of the system.

If you have only little experience with hydraulic systems, we would recommend to contact an appropriate work shop to have done that modification.



TOST
Flugzeuggerätebau

Tost GmbH Flugzeuggerätebau München
Thalkirchner Straße 62 ◆ 80337 München ◆ ☎ 089–544 599–0
Fax 089–544 599–70◆e-mail: info@tost.de◆ EASA DE.21G.0065