Retrofit kit to upgrade Twin-Astir to disk brake

	Description	Drawing	p/n
1.	Brake disk to fit the existing shoe brake wheel Bimbo	TN0112	057090
2.	Wheel bolts, 6 pcs. Allen screw M6×95		
3.	Brake assembly 30-9 for brake fluid DOT 4 with anchor plate		075820
4.	Hydraulic fitting straight		075830
5.	Torque plate assembly with tension rod and Spacer 35x30x18	T 9323-3 T 9102-4	055758
6.	Master cylinder type 7	T9114-03	058270
7.	Hydraulic hose 900 mm length		058390
8.	Hollow screw with copper gaskets		058550
9.	Support for master cylinder		059510
10.	General arrangement drawing and instructions	T9102-K	
	Retrofit kit complete		**051520**

Important notice:
Before you decide to start with the modification, please check, if the wheel halves of the existing shoe brake wheel are fixed together with 3 or 6 bolts. In case there are only 3 bolts, you need additionally a new hub, in order to perfo

Required work:
Turning of the brake disk centring, fitting hub and brake disk, installation of master cylinder, laying of the hydraulic hose, installation of the wheel unit(fit the spacer), filling with brake fluid DOT 4

If you have only little experience with hydraulic systems, we would recommend to contact an appropriate work shop to have done that modification.



TOST Flugzeuggerätebau
Tost GmbH Flugzeuggerätebau München
Thalkirchner Straße 62 ◆ 80337 München ◆ ☎ 089–544 599–0
Fax 089–544 599–70◆e-mail: info@tost.de◆ EASA DE.21G.0065