

# Retrofit kit to upgrade Swift/Jantar to disk brake

Description	Drawing	p/n
1. 5" disk brake wheel 115-25		055192
2. Brake assembly 30-9 for brake fluid DOT 4 with anchor plate		075820
3. Hydraulic fitting, straight		075830
4. Torque plate assembly with anchor bolt	T9510-1	055760
5. Master cylinder model 3		058230
6. Hydraulic house model 2b, 500 mm length		058765
7. Male stud elbow C 4 (90° connection to master cylinder)		058680
8. Straight coupling (connection hydraulic house / Cu pipe)		058620
9. Support for master cylinder (T9510-4)	T9510-4	059511
10. accessories for accentuation of the master cylinder lever	T9510-5/6/7	055761
11. Drawings and installation instruction + Service Bulletin	T9510-0 T9510-3	
<b>Retrofit kit complete</b>		<b>051570</b>

Required work: see description and installation instruction

If you have only little experience with hydraulic systems, we would recommend to contact an appropriate work shop to have done that modification.

